


ENGINEERING GRAPHICS WITH **AutoCAD® 2020**



JAMES D. BETHUNE



***Engineering Graphics
with AutoCAD® 2020***

Engineering Graphics with AutoCAD 2020

Table of Contents

Cover

Half Title

Title Page

Copyright Page

Preface

Online Instructor Supplementary Materials

Acknowledgments

Brief Contents

Contents

Chapter 1 Getting Started

1-1 Introduction

To Start a New Drawing

An Alternative Method to Starting a New Drawing

1-2 Tabs and Panels

To Access Additional Commands Within a Panel

Help Boxes for Commands

To Access Other Help Information

1-3 The Command Line Box

To Enter a Diameter Value

1-4 Command Tools

To Determine the Command That a Tool Represents

1-5 Starting a New Drawing

1-6 Naming a Drawing

To Start a New Drawing

To Save a New Drawing File

1-7 Drawing Units

To Specify or Change the Drawing Units

To Specify or Change the Precision of the Units System

To Specify or Change the Angle Units Value

1-8 Drawing Limits

Table of Contents

To Align the Drawing Limits with a Standard A3 (Metric) Paper Size

1-9 Grid and Snap

To Set the Grid and Snap Values

1-10 Sample Problem SP1-1

To Specify the Drawing Units

To Define the Drawing Precision

To Calibrate the Sheet Size

To Set the Grid and Snap Values

1-11 Save and Save As

To Use the Save and Save As Commands

1-12 Open

To Use the Open Command

1-13 Close

1-14 Exercise Problems

Chapter 2 Fundamentals of 2D Construction

2-1 Introduction

2-2 LineRandom Points

To Randomly Select Points (See Figure 2-2.)

To Exit a Command Sequence

To Create a Closed Area (See Figure 2-4.)

2-3 Erase

To Erase Individual Lines

To Erase a Group of Lines Simultaneously (See Figure 2-6.)

2-4 LineSnap Points

Problem: Draw a 3 × 5 Rectangle

2-5 LineDynamic Inputs

To Create Lines by Using Dynamic Input

To Access the Dynamic Input Settings

2-6 Construction Line

Other Construction Line Commands: Hor Ver Ang

Other Construction Line Command: Offset

2-7 Circle

To Draw a CircleRadius (See Figure 2-14.)

To Draw a CircleDiameter (See Figure 2-14.)

To Draw a Circle2 Points (See Figure 2-15.)

Table of Contents

To Draw a Circle3 Points (See Figure 2-15.)

To Draw a CircleTangent Tangent Radius

Quadrant-Sensitive Applications

2-8 Circle Centerlines

To Use the Center Mark Tool

2-9 Polyline

To Draw a Polyline (See Figure 2-20.)

To Verify That a Polyline Is a Single Entity

To Draw a Polyline: Arc (See Figure 2-21.)

Other Options with a Polyline Arc

To Draw Different Line Thicknesses (See Figure 2-23.)

2-10 Spline

2-11 Ellipse

To Draw an EllipseAxis Endpoint (See Figure 2-25.)

To Draw an EllipseCenter (See Figure 2-26.)

To Draw an EllipseArc (See Figure 2-27.)

To Draw an Ellipse by Defining Its Angle of Rotation About the Major Axis (See Figure 2-29.)

2-12 Rectangle

To Draw a Rectangle (See Figure 2-30.)

To Explode a Rectangle (See Figure 2-30.)

2-13 Polygon

To Draw a PolygonCenter Point (See Figure 2-31.)

To Draw a PolygonEdge Distance (See Figure 2-31.)

2-14 Point

To Change the Shape of a Point (See Figure 2-32.)

To Change the Size of a Point (See Figure 2-32.)

2-15 Text

To Use the Multiline Text Tool (See Figures 2-33 Through 2-39.)

The Text Editor Panel

To Access the Text Editor

To Change Text Height

To Change the Text Font

To Justify Text

To Justify the Text to the Right

The Symbol Options

Text Color

Table of Contents

2-16 Move

To Move an Object

2-17 Copy

To Copy an Object

To Draw Multiple Copies (See Figure 2-45.)

2-18 Offset (See Figure 2-46.)

2-19 Mirror (See Figure 2-47.)

2-20 Array

To Use the Rectangular Array Option

To Use the Polar Array Option

2-21 Rotate

To Rotate an Object (See Figure 2-51.)

2-22 Trim

To Use the Trim Command (See Figure 2-52.)

2-23 Extend

2-24 Break

To Use the Break Command

To Use the First Point Option

2-25 Chamfer

To Create a Chamfer

2-26 Fillet

To Draw a Fillet

2-27 Table

To Create a Table

2-28 Exercise Problems

Chapter 3 Advanced Commands

3-1 Introduction

3-2 Osnap

To Access the Osnap Commands

To Turn Osnap On

To Change the Size of the Osnap Cursor Box

3-3 OsnapEndpoint

To Snap to the Endpoint of an Existing Line

3-4 OsnapSnap From

To Move a Line

Table of Contents

To Change the Angle and Length of a Line

To Apply the Snap From Option to a Circle

3-5 OsnapMidpoint

To Draw a Circle About the Midpoint of a Line

3-6 OsnapIntersection

To Use the Osnap Intersection Command to Define an Ellipse

3-7 OsnapApparent Intersection

To Draw a Circle Centered About an Apparent Intersection

3-8 OsnapCenter

To Draw a Line to the Center Point of a Circle

3-9 OsnapQuadrant

To Draw a Line to One of a Circles Quadrant Points

3-10 OsnapPerpendicular

To Draw a Line Perpendicular to a Line

3-11 OsnapTangent

To Draw a Line Tangent to a Circle

3-12 OsnapNearest

To Draw a Line from a Point to the Nearest Selected Point on an Existing Line

3-13 Sample Problem SP3-1

3-14 Sample Problem SP3-2

3-15 Grips

To Turn the Grips Function Off

To Access the Grips Dialog Box

3-16 GripsExtend

To Extend the Length of a Line (See Figure 3-24.)

3-17 GripsMove

To Move an Object by Using Grips (See Figure 3-25.)

3-18 GripsRotate

To Rotate an Object by Using Grips (See Figure 3-26.)

3-19 GripsScale

To Change the Scale of an Object (See Figure 3-27.)

3-20 GripsMirror

To Mirror an Object (See Figure 3-28.)

3-21 Blocks

To Create a Block

Table of Contents

To Insert a Block

To Change the Scale of a Block

To Explode a Block

3-22 Working with Blocks

To Insert Blocks at Different Angles

To Insert Blocks with Different Scale Factors

To Use the Insert Dialog Box to Change the Shape of a Block

To Combine Blocks

3-23 Wblock

To Create a Wblock

To Verify that a Wblock Has Been Created

To Change the Size of a Wblock

3-24 Layers

To Create New Layers

To Change the Color and Linetype of a Layer

To Draw on Different Layers

To Change Layers

To Change the Scale of a Linetype

To Use the Match Tool

To Turn Layers Off

3-25 Attributes

To Add an Attribute to a Block

To Create a New Block that Includes Attributes

To Insert an Existing Block with Attributes

To Edit an Existing Attribute

3-26 Title Blocks with Attributes

3-27 Edit Polyline

To Create a Spline from a Given Polyline

3-28 Edit Spline

To Edit a Spline

3-29 Edit Text

To Change Existing Text

3-30 Constructing the Bisector of an AngleMethod I

3-31 Constructing the Bisector of an AngleMethod II

3-32 Constructing an Ogee Curve (S-Curve) with Equal Arcs

3-33 Constructing a Parabola

Table of Contents

- 3-34 Constructing a Hyperbola
- 3-35 Constructing a Spiral
- 3-36 Constructing a Helix
- 3-37 Designing by Using Shape Parameters
 - Design Problem DP3-1
 - Design Problem DP3-2
- 3-38 Exercise Problems

Chapter 4 Sketching

- 4-1 Introduction
- 4-2 Establishing Your Own Style
- 4-3 Graph Paper
- 4-4 Pencils
- 4-5 Lines
- 4-6 Proportions
- 4-7 Curves
- 4-8 Sample Problem SP4-1
- 4-9 Isometric Sketches
- 4-10 Sample Problem SP4-2
- 4-11 Oblique Sketches
- 4-12 Perspective Sketches
- 4-13 Working in Different Orientations
- 4-14 Exercise Problems

Chapter 5 Orthographic Views

- 5-1 Introduction
- 5-2 Three Views of an Object
- 5-3 Visualization
 - To Draw a Three-Dimensional Box
- 5-4 Hidden Lines
- 5-5 Hidden Line Conventions
- 5-6 Drawing Hidden Lines
 - To Add Hidden Linetypes to the Drawing
 - To Create a Hidden Layer for General Use
 - To Change Layers
- 5-7 Precedence of Lines

Table of Contents

5-8 Slanted Surfaces
5-9 Projection Between Views
5-10 Sample Problem SP5-1
5-11 Compound Lines
5-12 Sample Problem SP5-2
5-13 Oblique Surfaces
5-14 Sample Problem SP5-3
5-15 Rounded Surfaces
5-16 Sample Problem SP5-4
5-17 Holes
5-18 Holes in Slanted Surfaces
To Draw an Ellipse Representing a Projected Hole
To Draw Three Views of a Hole in a Slanted Surface
To Draw Three Views of a Hole Through an Oblique Surface
5-19 Cylinders
5-20 Sample Problem SP5-5
5-21 Cylinders with Slanted and Rounded Surfaces
5-22 Sample Problem SP5-6
5-23 Drawing Conventions and Cylinders
5-24 Irregular Surfaces
5-25 Sample Problem SP5-7
5-26 Hole Callouts
To Draw a Countersunk Hole (See Figure 5-65.)
5-27 Castings
5-28 Sample Problem SP5-8
5-29 Thin-Walled Objects
5-30 Sample Problem SP5-9
5-31 Intersections
5-32 Sample Problem SP5-10
5-33 Sample Problem SP5-11
5-34 Sample Problem SP5-12
5-35 Designing by Modifying an Existing Part
5-36 Drawing Standards
5-37 Third- and First-Angle Projections

Table of Contents

5-38 Exercise Problems

Chapter 6 Sectional Views

6-1 Introduction

6-2 Cutting Plane Lines

To Draw a Cutting Plane Line Method I

To Draw an Arrowhead

To Change the Size of an Arrowhead

To Draw a Cutting Plane Line Method II

To Draw Cutting Plane Lines

6-3 Section Lines

6-4 Hatch

To Hatch a Given Area

To Change Hatch Patterns

To Change the Spacing and Angle of a Hatch Pattern

6-5 Sample Problem SP6-1

6-6 Styles of Section Lines

6-7 Sectional View Location

6-8 Holes in Sections

6-9 Gradients

To Create a Gradient

6-10 Offset Sections

6-11 Multiple Sections

6-12 Aligned Sections

6-13 Drawing Conventions in Sections

6-14 Half, Partial, and Broken-Out Sectional Views

To Draw a Broken Line

6-15 Removed Sectional Views

6-16 Breaks

To Draw an S-Break (See Figure 6-40.)

6-17 Sectional Views of Castings

6-18 Exercise Problems

Chapter 7 Auxiliary Views

7-1 Introduction

7-2 Projection Between Normal and Auxiliary Views

Table of Contents

To Rotate the Drawings Axis System (See Figure 7-6.)

7-3 Sample Problem SP7-1

7-4 Transferring Lines Between Views

To Measure the Length of a Line

To Grip and Move a Line (See Figure 7-10.)

To Rotate and Move a Line

7-5 Sample Problem SP7-2

7-6 Projecting Rounded Surfaces

7-7 Sample Problem SP7-3

7-8 Projecting Irregular Surfaces

7-9 Sample Problem SP7-4

7-10 Sample Problem SP7-5

7-11 Partial Auxiliary Views

7-12 Sectional Auxiliary Views

7-13 Auxiliary Views of Oblique Surfaces

7-14 Secondary Auxiliary Views

To Draw the First Auxiliary View

To Draw the Secondary Auxiliary View

7-15 Sample Problem SP7-6

7-16 Secondary Auxiliary View of an Ellipse

7-17 Exercise Problems

Chapter 8 Dimensioning

8-1 Introduction

8-2 Terminology and Conventions

Some Common Terms (See Figure 8-2.)

Some Dimensioning Conventions (See Figure 8-3.)

Some Common Errors to Avoid (See Figure 8-4.)

8-3 Linear Dimension

To Create a Horizontal Dimension by Selecting Extension Line Locations or Origins (See Figure 8-5.)

To Create a Vertical Dimension

To Create a Horizontal Dimension by Selecting the Object to Be Dimensioned (See Figure 8-6.)

To Change the Default Dimension TextText Option

To Change the Default Dimension TextMtext Option

Table of Contents

To Edit an Existing Dimension

8-4 Dimension Styles

To Change the Scale of a Drawing

To Use the Text Option

8-5 Units

To Prevent a 0 from Appearing to the Left of the Decimal Point

To Change the Number of Decimal Places in a Dimension Value

8-6 Aligned Dimensions

To Create an Aligned Dimension (See Figures 8-29 and 8-30.)

The Select Object Option

8-7 Radius and Diameter Dimensions

To Create a Radius Dimension

To Alter the Default Dimension

To Remove the Center Mark from a Radius Dimension

To Create a Diameter Dimension

To Add Linear Dimensions to Given Centerlines

8-8 Angular Dimensions

To Create an Angular Dimension (See Figure 8-42.)

Avoid Overdimensioning

8-9 Ordinate Dimensions

To Move the Origin and the Origin Icon (See Figure 8-46.)

To Add Ordinate Dimensions to an Object

8-10 Baseline Dimensions

To Use the Baseline Dimension Tool (See Figure 8-50.)

8-11 Continue Dimension

To Use the Continue Dimension Command (See Figure 8-51.)

8-12 Quick Dimension

To Use the Quick Dimension Command

8-13 Center Mark

To Add Centerlines to a Given Circle

8-14 Mleader and Qleader

To Create a Leader Line with Text

To Draw a Curved Leader Line

To Draw a Leader Line with a Dot at Its End

8-15 Text Angle

Table of Contents

To Change the Angle of a Dimension Text

8-16 Tolerances

8-17 Dimensioning Holes

To Dimension Individual Holes

To Dimension Hole Patterns

8-18 Placing Dimensions

8-19 Fillets and Rounds

8-20 Rounded Shapes (Internal)

8-21 Rounded Shapes (External)

8-22 Irregular Surfaces

8-23 Polar Dimensions

8-24 Chamfers

8-25 Knurling

8-26 Keys and Keyseats

8-27 Symbols and Abbreviations

8-28 Symmetry and Centerline

8-29 Dimensioning to Points

8-30 Coordinate Dimensions

8-31 Sectional Views

8-32 Orthographic Views

8-33 Very Large Radii

To Create a Radius for Large Radii

8-34 Exercise Problems

Chapter 9 Tolerancing

9-1 Introduction

9-2 Direct Tolerance Methods

9-3 Tolerance Expressions

9-4 Understanding Plus and Minus Tolerances

9-5 Creating Plus and Minus Tolerances with AutoCAD

To Create Plus and Minus Tolerances by Using the Text Option

To Create Plus and Minus Tolerances with the Text Override Tool

To Use Dtext to Create a Plus and Minus Tolerance

To Use the Dimension Style Tool

The Symmetrical Method

Table of Contents

The Deviation Method

9-6 Limit Tolerances

9-7 Creating Limit Tolerances by Using AutoCAD

To Create a Limit Tolerance by Using the Dimension Style Manager

To Modify an Existing Dimension into a Limit Tolerance

9-8 Angular Tolerances

To Set the Precision for Angular Dimensions and Tolerances

To Create an Angular Dimension and Tolerance

9-9 Standard Tolerances

9-10 Double Dimensioning

9-11 Chain Dimensions and Baseline Dimensions

To Create Baseline Dimensions by Using AutoCAD

9-12 Tolerance Studies

To Calculate As Maximum Length

To Calculate As Minimum Length

9-13 Rectangular Dimensions

9-14 Hole Locations

9-15 Choosing a Shaft for a Toleranced Hole

For Linear Dimensions and Tolerances

9-16 Sample Problem SP9-1

9-17 Sample Problem SP9-2

9-18 Standard Fits (Metric Values)

Clearance Fits

Transition Fits

Interference Fits

9-19 Nominal Sizes

9-20 Hole and Shaft Basis

9-21 Sample Problem SP9-3

9-22 Standard Fits (Inch Values)

Fits Defined by Using Inch Values Are Classified as Follows

9-23 Sample Problem SP9-4

9-24 Preferred and Standard Sizes

9-25 Surface Finishes

9-26 Surface Control Symbols

Table of Contents

9-27 Design Problems

- Floating Condition

- Fixed Condition

- To Design a Hole Given a Fastener Size

9-28 Exercise Problems

Chapter 10 Geometric Tolerances

10-1 Introduction

10-2 Tolerances of Form

10-3 Flatness

10-4 Straightness

10-5 Straightness (RFS and MMC)

10-6 Circularity

10-7 Cylindricity

10-8 Geometric Tolerances Created by Using AutoCAD

- To Define a Datum

- To Define a Straightness Value

- To Create a Positional Tolerance

- To Create a Basic Dimension

- To Create Basic Dimensions from Existing Dimensions

- To Add a Limit Feature Tolerance to a Hole

- To Add a Positional Tolerance to the Holes Feature Tolerance

- To Add a Geometric Tolerance with a Leader Line

10-9 Tolerances of Orientation

10-10 Datums

10-11 Perpendicularity

10-12 Parallelism

10-13 Angularism

10-14 Profiles

10-15 Runouts

10-16 Positional Tolerances

10-17 Virtual Condition

- To Calculate the Virtual Condition for a Shaft

- To Calculate the Virtual Condition for a Hole

10-18 Floating Fasteners

Table of Contents

- 10-19 Sample Problem SP10-1
- 10-20 Sample Problem SP10-2
- 10-21 Fixed Fasteners
- 10-22 Sample Problem SP10-3
- 10-23 Design Problems
- 10-24 Exercise Problems

Chapter 11 Threads and Fasteners

- 11-1 Introduction
- 11-2 Thread Terminology
- 11-3 Thread Callouts (Metric Units)
- 11-4 Thread Callouts (English Units)
- 11-5 Thread Representations
 - To Draw a Detailed Thread Representation
 - To Create an Internal Detailed Thread Representation in a Sectional View
 - To Create a Schematic Thread Representation
 - To Create an Internal Schematic Thread Representation
 - To Create a Simplified Thread Representation
- 11-6 Orthographic Views of Internal Threads
- 11-7 Sectional Views of Internal Thread Representations
- 11-8 Types of Threads
- 11-9 How to Draw an External Square Thread
- 11-10 How to Draw an Internal Square Thread
- 11-11 How to Draw an External Acme Thread
- 11-12 Bolts and Nuts
- 11-13 Screws
- 11-14 Studs
- 11-15 Head Shapes
 - To Draw a Hexagon-Shaped (Hex) Head
 - To Draw a Square-Shaped Head
- 11-16 Nuts
 - To Draw a Hexagon-Shaped Finished Nut
 - To Draw a Locking Nut
- 11-17 Sample Problem SP11-1
- 11-18 Sample Problem SP11-2

Table of Contents

11-19 Standard Screws

11-20 Setscrews

11-21 Washers

To Draw a Plain Washer (See Figure 11-35.)

11-22 Keys

11-23 Rivets

11-24 Springs

To Draw a Detailed Representation of an Extension Spring

To Draw a Detailed Representation of a Compression Spring

11-25 Tool Palettes

To Create a Shoulder Screw

To Change the Scale of a Tool Palette Block

To Modify the Block

11-26 Exercise Problems

Chapter 12 Working Drawings

12-1 Introduction

12-2 Assembly Drawings

12-3 Drawing Formats (Templates)

To Add a Drawing Template

12-4 Title Block

Drawing Titles (Names)

Drawing Numbers

Company Name

Scale

Release Date

Sheet

12-5 Revision Block

12-6 Tolerance Block

12-7 Release Block

Drawn

Checked

Design

Stress/Wts

Materials

Customer

Table of Contents

12-8 Parts List (Bill of MaterialsBOM)

12-9 Detail Drawings

12-10 First-Angle Projection

12-11 Drawing Notes

12-12 Design Layouts

12-13 Sample Problem SP12-1

To Create the Design Layout (See Figure 12-29.)

To Create a Drawing Using Layers

To Create a Drawing from a Layout

12-14 Sample Problem SP12-2

To Create an Assembly Drawing

12-15 Sample Problem SP12-3

12-16 Exercise Problems

Chapter 13 Gears, Bearings, and Cams

13-1 Introduction

13-2 Types of Gears

13-3 Gear TerminologySpur

For Spur Gears Using English Units

For Spur Gears Using Metric Units

13-4 Spur Gear Drawings

13-5 Sample Problem SP13-1

13-6 Sample Problem SP13-2

To Draw Meshing Spur Gears (See Figure 13-9B.)

13-7 Sample Problem SP13-3

13-8 Selecting Spur Gears

13-9 Center Distance Between Gears

13-10 Sample Problem SP13-4

13-11 Combining Spur Gears

13-12 Gear TerminologyBevel

13-13 How to Draw Bevel Gears

To Draw a Matched Set of Beveled Gears

13-14 Worm Gears

13-15 Helical Gears

13-16 Racks

Table of Contents

- 13-17 Ball Bearings
- 13-18 Sample Problem SP13-5
- 13-19 Bushings
- 13-20 Sample Problem SP13-6
- 13-21 Cam Displacement Diagrams
 - To Set Up a Displacement Diagram
- 13-22 Cam Motions
 - Uniform Motion
 - Modified Uniform Motion
 - Harmonic Motion
 - Uniform Acceleration and Deceleration
- 13-23 Cam Followers
- 13-24 Sample Problem SP13-7
- 13-25 Exercise Problems

Chapter 14 Fundamentals of 3D Drawing

- 14-1 Introduction
- 14-2 The World Coordinate System
 - To Change the Background Color to White
- 14-3 Viewpoints
 - To Change the Viewpoint by Using the Views Panel
 - To Change the Viewpoint by Using the View Command
 - To Return to the Original WCS Orientation
- 14-4 Perspective and Parallel Grids
 - To Create a Drawing with a Perspective Grid
 - To Return to the 2D WCS
- 14-5 3D Modeling
 - To Access the 3D Modeling Mode
- 14-6 User Coordinate System (UCS)
 - To Draw a Solid Box
 - To Create a UCS on the Top Surface
 - To Save a UCS
 - To Return to the WCS
 - To Return to a Saved UCS
 - To Define a UCS by Using the 3-Point Tool
- 14-7 Editing a Solid Model

Table of Contents

To Change the Length and Width of a Solid Model

14-8 Visual Styles

To Change Visual Styles

14-9 Rotating a UCS Axis

To Rotate About the X-Axis

14-10 Sample Problem SP14-1

14-11 Visual Errors

To Change Views

14-12 Sample Problem SP14-2

To Draw a Circle on the Upper Front Surface

To Draw a Rectangle on the Top Surface

To Draw an Ellipse on the Left Vertical Surface

14-13 Orthographic Views

To Create Four Viewports

To Create Orthographic Views

14-14 Line Thickness

To Use the Thickness Command

To Draw a Curve by Using Thickness (See Figure 14-46.)

14-15 Using the Thickness Command to Create Objects

To Draw the Box

To Create a New UCS

To Draw the Right Cylinder

To Draw the Top Cylinder

To Return the Drawing to Its Original Settings

14-16 Exercise Problems

Chapter 15 Modeling

15-1 Introduction

15-2 Box

To Draw a Box by Using the Corner Option (See Figure 15-2.)

To Change the Visual Style

To Draw a Box from Given Dimensions

To Draw a Cube (See Figure 15-5.)

To Use Dynamic Grips

15-3 Sphere

To Draw a Sphere (See Figure 15-7.)

Table of Contents

15-4 Cylinder

To Draw a Cylinder with a Circular Base

To Draw a Cylinder with an Elliptical Base

15-5 Cone

To Draw a Cone with an Elliptical Base (See Figure 15-10.)

To Draw a Cone with a Circular Base (See Figure 15-11.)

15-6 Wedge

To Draw a Wedge by Defining Its Corner Point (See Figure 15-13.)

To Draw a Wedge by Defining Its Center Point (See Figure 15-14.)

To Align a Wedge with an Existing Wedge

15-7 Torus

To Draw a Torus

15-8 Extrude

To Extrude a 2D Polyline

To Create a Polyline from Line Segments

15-9 Revolve

To Create a Revolved Solid Object

15-10 Helix

15-11 Polysolid

15-12 Loft

15-13 Intersect

15-14 Union and Subtract

To Union Two Objects

To Subtract an Object

15-15 Solid Modeling and UCSs

15-16 Combining Solid Objects

To Set Up the Drawing

To Draw the First Box

To Create the Internal Open Volume

To Create the Top Cutout

To Create a Box

To Create a Wedge

15-17 Intersecting Solids

To Set Up the Drawing

To Draw the Cone

Table of Contents

- To Draw the Cylinder
- To Complete the 3D Drawing
- To Create the Viewports for the Orthographic Views

15-18 Solid Models of Castings

- To Draw the Basic Shape
- To Create a Polyline from the Basic Shape
- To Extrude the Shape
- To Add the Holes
- To Create the Rounded Edges

15-19 Thread Representations in Solid Models

15-20 List

15-21 Massprop

15-22 Face and Edge Editing

- To Extrude a Face (See Figure 15-65.)
- To Extrude a Face Along a Path
- To Extrude Two Faces at the Same Time (See Figure 15-67.)
- To Move a Face (See Figure 15-68.)
- To Offset Faces (See Figure 15-69.)
- To Rotate a Face (See Figure 15-70.)
- To Taper a Face
- To Copy a Face
- To Copy Edges (See Figure 15-73.)
- To Imprint an Object (See Figure 15-74.)

15-23 Exercise Problems

Index

Chapter 16 Projects (Online Only)

- 16-1 Introduction
- 16-2 Project 1: Milling Vise
- 16-3 Project 2: Tenon Jig

Appendix (Online Only)

- A-1 Wire and Sheet Metal Gauges
- A-2 American Standard Clearance Locational Fits
- A-3 American Standard Running and Sliding Fits
- A-4 American Standard Transition Locational Fits
- A-5 American Standard Interference Locational Fits

Table of Contents

A-6 American Standard Force and Shrink Fits	
A-7 Preferred Clearance FitsCylindrical Fits	
A-8 Preferred Transition and Interference FitsCylindrical Fits	
A-9 Preferred Clearance FitsCylindrical Fits	
A-10 Preferred Transition and Interference FitsCylindrical Fits	
A-11 American National Standard Type A Plain Washers	
A-12 American National Standard Helical Spring Lock Washers	
A-13 American National Standard InternalExternal Tooth Lock Washers	
A-14 British Standard Bright Metal WashersMetric Series	
A-15 American National Standard and Unified Standard Square Bolts	
A-16 American National Standard and Unified Standard Hex Head Screws	
A-17 Coarse-Thread Series, UNC, UNRC, and NCBasic Dimensions	
A-18 Fine-Thread Series, UNC, UNRC, and NCBasic Dimensions	
A-19 American National Standard General-Purpose Acme Screw Thread FormBasic Dimensions	
A-20 60° Stub Threads	
A-21 American National Standard Slotted 100° Flat Countersunk HeadMachine Screws	
A-22 American National Standard Slotted Truss Head Machine Screws	
A-23 American National Standard Plain and Slotted Hexagon Head Machine Screws	
A-24 Slotted Round Head Machine Screws	
A-25 American National Standard Square Head Setscrews	
A-26 American National Standard Square Head Setscrews	
A-27 American National Standard Slotted Headless Setscrews	
A-28 Lengths for Threaded Fasteners	
A-29 Lengths for Metric Threaded Fasteners	
A-30 American National Standard Square and Hexagon Machine Screw Nuts	
A-31 Standard Twist Drill Sizes (Inches)	
A-32 Standard Twist Drill Sizes (Millimeters)	
A-33 Metric ThreadsPreferred Sizes	
A-34 Standard Thread SizesInches	
A-35 Thread Lengths	
A-36 FastenersStandard Lengths	

Table of Contents

A-37 American National Standard Plain Washers

A-38 Flat WashersMetric Sizes