MODERN GRAPHICS Communication

6th Edition

Frederick E. Giesecke | Shawna Lockhart Marla Goodman | Cindy M. Johnson



4ths	8ths	16ths	32nds	64ths	To 4 Places	To 3 Places	To 2 Places	Milli- meters	4ths	8ths	16ths	32nds	64ths	To 4 Places	To 3 Places	To 2 Places	Mill mete
14	1480	1/16	1 32—	$\frac{1}{64}$ —	.0156	.016	.02	.397		9/16-		17 32	33 64	.5156	.516	.52	13.0
				3 64	.0312 .0469	.031 .047	.03 .05	.794 1.191					35	.5312 .5469	.531 .547	.53 .55	13.4 13.8
				64	.0409	.062	.06	1.588			9		35 64	.5625	.562	.56	14.2
			3 32 —	<u>5</u> 64 –	.0781	.078	.08	1.984		'	10		37 64	.5781	.578	.58	14.6
					.0938	.094	.09	2.381			19 32		.5938	.594	.59	15.0	
				7 64 –	.1094 .1250	.109 .125	.11 .12	2.778 3.175		5			39 64	.6094 .6250	.609 .625	.61 .62	15.4 15.8
		3 16 —	<u>5</u> 32	9 64 –	.1406	.141	.14	3.572		5 -		2 <u>1</u>	41 64	.6406	.641	.62 .64	16.2
					.1562	.156	.16	3.969					64	.6562	.656	.66	16.0
				11 64 —	.1719	.172	.17	4.366					43 64	.6719	.672	.67	17.0
			7 32 —	13 64	.1875 .2031	.188 .203	.19 .20	4.762 5.159		11 16 -	16		45	.6875 .7031	.688 .703	.69 .70	17.4 17.8
				64	.2188	.219	.22	5.556	3 4			23 32	4 <u>5</u> 64	.7188	.703 .719	.70 .72	18.
				15 64	.2344	.234	.23	5.953				25 32 27 32	47 64	.7344	.734	.73	18.
					.2500	.250	.25	6.350						.7500	.750	.75	19.
			9/32	17 64 —	.2656	.266 .281	.27 .28	6.747 7.144					49 64	.7656	.766	.77	19.4
				19 64	.2812 .2969	.297	.28 .30	7.144 7.541					<u>51</u> 64	.7812 .7969	.781 .797	.78 .80	19.8 20.2
				64	.3125	.312	.31	7.938			13		64	.8125	.812	.81	20.6
			11 32	21 64 –	.3281	.328	.33	8.334					53 64	.8281	.828	.83	21.0
				22	.3438	.344	.34	8.731		7			55	.8438	.844	.84	21.4
				23 64 —	.3594 .3750	.359 .375	.36 .38	9.128 9.525					<u>55</u> 64	.8594 .8750	.859 .875	.86 .88	21.8
		7 16	13 32	25 64	.3750	.391	.39	9.922		8	29 32	<u>57</u> 64	.8906	.891	.89	22.6	
					.4062	.406	.41	10.319					.9062	.906	.91	23.0	
				27 64 –	.4219	.422		10.716			15 16		<u>59</u> 64	.9219	.922	.92	23.4
			15 32	<u>29</u> 64 –	.4375 .4531	.438 .453		11.112 11.509				31 32	<u>61</u> —	.9375 .9531	.938 .953	.94 .95	23.8 24.2
				64	.4531	.469		11.906					64	.9688	.969	.95 .97	24.2
			32	3 <u>1</u>	.4844	.4844 .484	.48	12.303					63 64	.9844	.984	.98	25.0
					.5000	.500	.50	12.700						1.0000	1.000	1.00	25.4

Metric measurements may be set off directly on drawings with the metric scale. Decimal measurements may be set off directly on drawings with the engineers' scale or the decimal scale.

Symbols for Instructors' Corrections

C Show construction

Show dimensions; show given or required data

/ Improve form or spacing

H Too heavy

Not heavy enough

NOT Not dark enough

Sharpen pencil or compass lead

6L Use guidelines

∠ Improve arrowheads

Error in circled area

Modern Graphics Communication

Table of Contents

Cover

Title Page

Copyright Page

BRIEF CONTENTS

CONTENTS

CHAPTER ONE: THE WORLDWIDE GRAPHIC LANGUAGE FOR DESIGN

UNDERSTANDING THE ROLE OF TECHNICAL DRAWINGS

The Design Process

Concurrent Engineering

Computer-Aided Design and Product Development

Designing Quality into Products

The Digital Database

1.1 GRAPHICS TOOLS IN ACTION

Design Phase: Problem Identification

Design Phase: Ideation

Design Phase: Decision Process/Design Selection

Design Phase: Refinement Design Phase: Analysis

Design Phase: Decision Process/Design Selection

Design Phase: Implementation
Design Phase: Documentation

1.2 RAPID PROTOTYPING

1.3 DRAFTING STANDARDS

1.4 CREATIVITY TECHNIQUES

Examine Manufactured Products

Study the Natural World

Watch the Web

Research Patent Drawings

Design Groups

1.5 PRODUCT DEFINITION

1.6 SHOWING THE DESIGN PROCESS IN A PORTFOLIO



KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

REVERSE ENGINEERING PROJECTS

Can Opener Project

Locking Pliers Project

CHAPTER TWO: LAYOUTS AND LETTERING

UNDERSTANDING PROJECTION

Types of Projection

Drawing Vocabulary

- 2.1 ALPHABET OF LINES
- 2.2 FREEHAND LINES
- 2.3 MEASUREMENT SYSTEMS

U.S. Customary Units

The Metric System

- 2.4 DRAWING SCALE
- 2.5 SPECIFYING THE SCALE ON A DRAWING
- 2.6 LETTERING
- 2.7 LETTERING STANDARDS
- 2.8 USING GUIDELINES FOR HAND LETTERING
- 2.9 VERTICAL AND INCLINED LETTERS AND NUMERALS
- 2.10 FRACTIONS
- 2.11 SPACING OF LETTERS AND WORDS
- 2.12 LETTERING FOR TITLES
- 2.13 DRAWING PENCILS
- 2.14 TEMPLATES
- 2.15 CAD TOOLS
- 2.16 SKETCHING AND DRAWING MEDIA
- 2.17 STANDARD SHEETS
- 2.18 STANDARD LAYOUT ELEMENTS

Margins and Borders

Zones

Typical Letter Sizes



Title Block

2.19 LAYOUTS

2.20 PLANNING YOUR DRAWING OR SKETCH

Show Details Clearly

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

Drawing Exercises

Lettering Exercises

CHAPTER THREE: VISUALIZATION AND SKETCHING

UNDERSTANDING SOLID OBJECTS

Types of Solids

UNDERSTANDING SKETCHING TECHNIQUES

Analyzing Complex Objects

Viewpoint

Shading

Edges and Vertices

Points and Lines

Angles

Drawings and Sketches

Freehand Sketching

3.1 TECHNIQUE OF LINES

Lineweights

3.2 SKETCHING STRAIGHT LINES

Blocking in a Freehand Drawing

3.3 SKETCHING CIRCLES, ARCS, AND ELLIPSES

Circles

Sketching Arcs

Sketching Ellipses

- 3.4 MAINTAINING PROPORTIONS
- 3.5 ONE-VIEW DRAWINGS
- 3.6 PICTORIAL SKETCHING
- 3.7 PROJECTION METHODS
- 3.8 AXONOMETRIC PROJECTION



Axonometric Projections and 3D Models

3.9 ISOMETRIC PROJECTION

Isometric Axes

Nonisometric Lines

Isometric Scales

- 3.10 ISOMETRIC DRAWINGS
- 3.11 MAKING AN ISOMETRIC DRAWING
- 3.12 OFFSET LOCATION MEASUREMENTS

Isometric Drawings of Inclined Surfaces

- 3.13 HIDDEN LINES AND CENTERLINES
- 3.14 ANGLES IN ISOMETRIC
- 3.15 IRREGULAR OBJECTS
- 3.16 CURVES IN ISOMETRIC
- 3.17 TRUE ELLIPSES IN ISOMETRIC
- 3.18 ORIENTING ELLIPSES IN ISOMETRIC DRAWINGS
- 3.19 DRAWING ISOMETRIC CYLINDERS
- 3.20 SCREW THREADS IN ISOMETRIC
- 3.21 ARCS IN ISOMETRIC
- 3.22 SPHERES IN ISOMETRIC
- 3.23 OBLIQUE SKETCHES

Appearance of Oblique Drawings

Choosing the Front Surface

Angle of Receding Lines

3.24 LENGTH OF RECEDING LINES

Cavalier Projection

Cabinet Projection

- 3.25 CHOICE OF POSITION IN OBLIQUE DRAWINGS
- 3.26 ELLIPSES FOR OBLIQUE DRAWINGS
- 3.27 ANGLES IN OBLIQUE PROJECTION
- 3.28 SKETCHING ASSEMBLIES
- 3.29 SKETCHING PERSPECTIVES

The Three Types of Perspective

Birds-Eye View Versus Worms-Eye View

3.30 CURVES AND CIRCLES IN PERSPECTIVE



- 3.31 SHADING
- 3.32 COMPUTER GRAPHICS
- 3.33 DRAWING ON DRAWING

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

SKETCHING EXERCISES

CHAPTER FOUR: GEOMETRY FOR MODELING AND DESIGN

COORDINATES FOR 3D CAD MODELING

Specifying Location

GEOMETRIC ENTITIES

Points

Lines

Planes

Circles

Arcs

- 4.1 MANUALLY BISECTING A LINE OR CIRCULAR ARC
- 4.2 DRAWING TANGENTS TO TWO CIRCLES
- 4.3 DRAWING AN ARC TANGENT TO A LINE OR ARC AND THROUGH A POINT
- 4.4 BISECTING AN ANGLE
- 4.5 DRAWING A LINE THROUGH A POINT AND PARALLEL TO A LINE
- 4.6 DRAWING A TRIANGLE WITH SIDES GIVEN
- 4.7 DRAWING A RIGHT TRIANGLE WITH HYPOTENUSE AND ONE SIDE GIVEN
- 4.8 LAYING OUT AN ANGLE
- 4.9 DRAWING AN EQUILATERAL TRIANGLE
- 4.10 POLYGONS
- 4.11 DRAWING A REGULAR PENTAGON
- 4.12 DRAWING A HEXAGON
- 4.13 ELLIPSES
- 4.14 SPLINE CURVES
- 4.15 GEOMETRIC RELATIONSHIPS
- 4.16 SOLID PRIMITIVES

Making Complex Shapes with Boolean Operations

4.17 RECOGNIZING SYMMETRY



Right- and Left-Hand Parts

Parting-Line Symmetry

4.18 EXTRUDED FORMS

Swept Shapes

- 4.19 REVOLVED FORMS
- 4.20 IRREGULAR SURFACES
- 4.21 USER COORDINATE SYSTEMS
- 4.22 TRANSFORMATIONS

Geometric Transformations

Viewing Transformations

KEY WORDS

CHAPTER SUMMARY

SKILLS SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

CHAPTER FIVE: MODELING AND DESIGN

REFINEMENT AND MODELING

KINDS OF MODELS

Descriptive Models

Analytical Models

5.1 2D MODELS

Paper Drawings

2D CAD Models

2D Constraint-Based Modeling

5.2 3D MODELS

Physical Models

3D CAD Models

5.3 TYPES OF 3D MODELS

Wireframe Models

Surface Models

Solid Models

5.4 CONSTRAINT-BASED MODELING

5.5 CONSTRAINTS DEFINE THE GEOMETRY

Feature-Based Modeling

5.6 PLANNING PARTS FOR DESIGN FLEXIBILITY



5.7 SKETCH CONSTRAINTS

Overconstrained Sketches

Underconstrained Sketches

Applying Constraints

Setting the Base Point

5.8 THE BASE FEATURE

Adding Features to the Model

Parent-Child Relationships

Datum Planes and Surfaces

5.9 EDITING THE MODEL

Standard Features

Working with Built-in Features

Complex Shapes

5.10 CONSTRAINT-BASED MODELING MODES

Assemblies

Drawings from the Model

5.11 CHOOSING THE RIGHT MODELING METHOD

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

CHAPTER SIX: ORTHOGRAPHIC PROJECTION

UNDERSTANDING PROJECTION

Views of Objects

The Six Standard Views

Principal Dimensions

Projection Method

The Glass Box

Spacing between Views

Transferring Depth Dimensions

Measuring from a Reference Surface

Necessary Views

Orientation of the Front View

First- and Third-Angle Projection

Third-Angle Projection

Alternative Arrangements for Third-Angle Projection



First-Angle Projection

Projection System Drawing Symbol

Hidden Lines

Centerlines

- 6.1 HIDDEN LINE TECHNIQUE
- **6.2 PRECEDENCE OF LINES**
- **6.3 CENTERLINES**
- 6.4 LAYING OUT A DRAWING
- 6.5 DEVELOPING VIEWS FROM 3D MODELS

Placing the Views

Isometric Views

6.6 VISUALIZATION

Surfaces, Edges, and Corners

- 6.7 VIEWS OF SURFACES
- **6.8 NORMAL SURFACES**
- 6.9 INCLINED SURFACES
- 6.10 OBLIQUE SURFACES
- **6.11 EDGES**
- 6.12 NORMAL EDGES
- 6.13 INCLINED EDGES
- 6.14 OBLIQUE EDGES
- 6.15 PARALLEL EDGES
- 6.16 ANGLES
- 6.17 VERTICES
- 6.18 INTERPRETING POINTS
- 6.19 INTERPRETING LINES
- 6.20 SIMILAR SHAPES OF SURFACES
- 6.21 INTERPRETING VIEWS
- 6.22 MODELS

Rules for Visualizing from a Drawing: Putting It All Together

- 6.23 PROJECTING A THIRD VIEW
- 6.24 BECOMING A 3D VISUALIZER

KEY WORDS

CHAPTER SUMMARY



REVIEW QUESTIONS CHAPTER EXERCISES

CHAPTER SEVEN: 2D DRAWING REPRESENTATION

PRACTICES FOR 2D DOCUMENTATION DRAWINGS

Common Manufactured Features

Conventional Representations

Intersections and Tangencies

Removed Views

- 7.1 VISUALIZING AND DRAWING COMPLEX CYLINDRICAL SHAPES
- 7.2 CYLINDERS WHEN SLICED
- 7.3 CYLINDERS AND ELLIPSES
- 7.4 INTERSECTIONS AND TANGENCIES

Intersections of Cylinders

- 7.5 FILLETS AND ROUNDS
- 7.6 RUNOUTS
- 7.7 CONVENTIONAL EDGES
- 7.8 NECESSARY VIEWS
- 7.9 PARTIAL VIEWS

Showing Enlarged Details

Conventional Breaks

- 7.10 ALIGNMENT OF VIEWS
- 7.11 REMOVED VIEWS
- 7.12 RIGHT-HAND AND LEFT-HAND PARTS
- 7.13 REVOLUTION CONVENTIONS

Common Hole Features Shown in Orthographic Views

Common Features Shown in Orthographic Views

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

CHAPTER EIGHT: SECTION VIEWS

UNDERSTANDING SECTIONS

Sections of Single Parts

Full Sections



The Cutting Plane

Lines behind the Cutting Plane

- 8.1 PLACEMENT OF SECTION VIEWS
- 8.2 LABELING CUTTING PLANES
- 8.3 LINE PRECEDENCE
- 8.4 RULES FOR LINES IN SECTION VIEWS
- 8.5 CUTTING-PLANE LINE STYLE

Visualizing Cutting-Plane Direction

8.6 SECTION-LINING TECHNIQUE

Section Lining Large Areas

Section-Lining Symbols

Section Lining in CAD

- 8.7 HALF SECTIONS
- 8.8 BROKEN OUT SECTIONS
- 8.9 REVOLVED SECTIONS
- 8.10 REMOVED SECTIONS
- 8.11 OFFSET SECTIONS
- 8.12 RIBS IN SECTION
- 8.13 ALIGNED SECTIONS
- 8.14 PARTIAL VIEWS
- 8.15 INTERSECTIONS IN SECTIONS
- 8.16 CONVENTIONAL BREAKS AND SECTIONS
- 8.17 ASSEMBLY SECTIONS

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

CHAPTER NINE: AUXILIARY VIEWS

UNDERSTANDING AUXILIARY VIEWS

The Auxiliary Plane

Primary Auxiliary Views

Visualizing an Auxiliary View as a Revolved Drawing

Classification of Auxiliary Views

Successive Auxiliary Views



Secondary Auxiliary Views

Reference Planes

- 9.1 USING TRIANGLES TO SKETCH AUXILIARY VIEWS
- 9.2 USING GRID PAPER TO SKETCH AUXILIARY VIEWS
- 9.3 USING CAD TO CREATE AUXILIARY VIEWS
- 9.4 CIRCLES AND ELLIPSES IN AUXILIARY VIEWS
- 9.5 HIDDEN LINES IN AUXILIARY VIEWS
- 9.6 PARTIAL AUXILIARY VIEWS
- 9.7 HALF AUXILIARY VIEWS
- 9.8 REVERSE CONSTRUCTION
- 9.9 AUXILIARY SECTIONS
- 9.10 VIEWING-PLANE LINES AND ARROWS
- 9.11 USES OF AUXILIARY VIEWS
- 9.12 TRUE LENGTH OF A LINE
- 9.13 POINT VIEW OF A LINE

Showing the Point View of a Line

9.14 EDGE VIEW OF A PLANE

Showing the Edge View of a Plane

9.15 TRUE SIZE OF AN OBLIQUE SURFACE

Showing the True Size and Shape of an Oblique Surface

9.16 DIHEDRAL ANGLES

UNDERSTANDING DEVELOPMENTS AND INTERSECTIONS

Surface Terminology

Developable Surfaces

Principles of Intersections

9.17 DEVELOPMENTS

Finding the Intersection of a Plane and a Prism and Developing the Prism

Finding the Intersection of a Plane and a Cylinder and Developing the Cylinder

9.18 HEMS AND JOINTS FOR SHEET METAL AND OTHER MATERIALS

9.19 MORE EXAMPLES OF DEVELOPMENTS AND INTERSECTIONS

Developing a Plane and an Oblique Prism

Developing a Plane and an Oblique Cylinder

Developing a Plane and a Pyramid

Developing a Plane and a Cone

Developing a Hood and Flue



a	20	TRA	NICI	TION	DIE	CES
Э.	/()	1 P	ハクシ	עול או ו		いてつ

9.21 TRIANGULATION

9.22 DEVELOPING A TRANSITION PIECE CONNECTING RECTANGULAR PIPES ON THE SAME AXIS

9.23 DEVELOPING A PLANE AND A SPHERE

9.24 REVOLUTION

Axis of Revolution

Creating a Revolved Drawing

9.25 PRIMARY AND SUCCESSIVE REVOLUTIONS

9.26 TRUE LENGTH OF A LINE: REVOLUTION METHOD

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

Design Project

Auxiliary View Exercises

Revolution Exercises

Development Exercises

CHAPTER TEN: MODELING FOR MANUFACTURE AND ASSEMBLY DESIGN FOR MANUFACTURE, ASSEMBLY, DISASSEMBLY, AND SERVICE

10.1 ASSEMBLY MODELS

Constraint-Based Assemblies

Choosing the Parent Part

Assembly Constraints

Managing Assembly Files

10.2 ASSEMBLIES AND DESIGN

Layout Drawings

Assembling to a Skeleton

Global Parameters

Seed Parts

Constraint-Based Drawing Elements

10.3 ASSEMBLIES AND SIMULATION

10.4 PARTS FOR ASSEMBLIES

Standard Parts

Fastener Libraries



10.5 USING YOUR MODEL TO CHECK FITS

Interference Checking

Accessibility Checking

10.6 MANUFACTURING PROCESSES

Designing Plastic Parts

Cast Parts

Modeling Machined Parts

Modeling Sheet Metal Parts

Other Methods of Production

10.7 DOS AND DONTS OF PRACTICAL DESIGN

Casting Design

Practical Considerations

10.8 MANUFACTURING MATERIALS

Material Assignment in Models

- 10.9 APPEARANCE, SERVICE LIFE, AND RECYCLING
- 10.10 DIMENSIONAL ACCURACY AND SURFACE FINISH
- 10.11 NET-SHAPE MANUFACTURING
- 10.12 COMPUTER-INTEGRATED MANUFACTURING
- 10.13 SHARED MANUFACTURING
- 10.14 MANUFACTURING METHODS AND THE DRAWING
- 10.15 MODELING FOR TESTING AND REFINEMENT

10.16 DETERMINING MASS PROPERTIES

Understanding Mass Property Calculations

10.17 EXPORTING DATA FROM THE DATABASE

File Formats

Common Formats for Export

Vector versus Raster Data

10.18 DOWNSTREAM APPLICATIONS

Spreadsheets

Equation Solvers

Finite Element Analysis

Simulation Software

Human Factors

Integrated Modeling and Design Software

10.19 PROTOTYPING YOUR DESIGN



Rapid Prototyping

Translating the Model

Rapid Prototyping Systems

Rapid Tooling

KEY WORDS

CHAPTER SUMMARY

SKILLS SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

Mass Properties Exercises

CHAPTER ELEVEN: DIMENSIONING

UNDERSTANDING DIMENSIONING

Three Aspects of Good Dimensioning

Tolerance

Geometric Breakdown

- 11.1 LINES USED IN DIMENSIONING
- 11.2 USING DIMENSION AND EXTENSION LINES
- 11.3 ARROWHEADS
- 11.4 LEADERS
- 11.5 DRAWING SCALE AND DIMENSIONING
- 11.6 DIRECTION OF DIMENSION VALUES AND NOTES
- 11.7 DIMENSION UNITS
- 11.8 MILLIMETER VALUES
- 11.9 DECIMAL-INCH VALUES
- 11.10 RULES FOR DIMENSION VALUES
- 11.11 RULES FOR ROUNDING DECIMAL DIMENSION VALUES
- 11.12 DUAL DIMENSIONING
- 11.13 COMBINATION UNITS
- 11.14 DIMENSIONING SYMBOLS
- 11.15 PLACING AND SHOWING DIMENSIONS LEGIBLY

Rules for Placing Dimensions Properly

- 11.16 SUPERFLUOUS DIMENSIONS
- 11.17 DIMENSIONING ANGLES
- 11.18 DIMENSIONING ARCS



- 11.19 FILLETS AND ROUNDS
- 11.20 SIZE DIMENSIONING: PRISMS
- 11.21 SIZE DIMENSIONING: CYLINDERS
- 11.22 SIZE DIMENSIONING: HOLES
- 11.23 APPLYING STANDARD DIMENSIONING SYMBOLS
- 11.24 DIMENSIONING COUNTERBORES AND SPOTFACES WITH FILLETS
- 11.25 DIMENSIONING TRIANGULAR PRISMS, PYRAMIDS, AND CONES
- 11.26 DIMENSIONING CURVES
- 11.27 DIMENSIONING CURVED SURFACES
- 11.28 DIMENSIONING ROUNDED-END SHAPES
- 11.29 DIMENSIONING THREADS
- 11.30 DIMENSIONING TAPERS
- 11.31 DIMENSIONING CHAMFERS
- 11.32 SHAFT CENTERS
- 11.33 DIMENSIONING KEYWAYS
- 11.34 DIMENSIONING KNURLS
- 11.35 FINISH MARKS
- 11.36 SURFACE ROUGHNESS

Applications of Surface Roughness Symbols

- 11.37 LOCATION DIMENSIONS
- 11.38 MATING DIMENSIONS
- 11.39 COORDINATE DIMENSIONING
- 11.40 TABULAR DIMENSIONS
- 11.41 DIMENSIONING FOR NUMERICALLY- CONTROLLED MACHINING
- 11.42 MACHINE, PATTERN, AND FORGING DIMENSIONS
- 11.43 SHEET METAL BENDS
- **11.44 NOTES**
- 11.45 STANDARDS
- 11.46 DOS AND DONTS OF DIMENSIONING

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES



CHAPTER TWELVE: TOLERANCING

UNDERSTANDING TOLERANCE

Tolerance

Quality Control

Definitions for Size Designation

Variations in Form

Tolerance Envelope

Implied Right Angles

Fits between Mating Parts

Selective Assembly

Hole System

Shaft System

12.1 SPECIFYING TOLERANCES

12.2 GENERAL TOLERANCE NOTES

12.3 LIMIT TOLERANCES

Single-Limit Dimensioning

12.4 PLUS-OR-MINUS TOLERANCES

12.5 TOLERANCE STACKING

Chained or Continuous Dimensioning

Baseline Dimensioning

12.6 USING AMERICAN NATIONAL STANDARD LIMITS AND FIT TABLES

- 12.7 TOLERANCES AND MACHINING PROCESSES
- 12.8 METRIC SYSTEM OF TOLERANCES AND FITS
- 12.9 PREFERRED SIZES
- 12.10 PREFERRED FITS
- 12.11 GEOMETRIC DIMENSIONING AND TOLERANCING
- 12.12 SYMBOLS FOR TOLERANCES OF POSITION AND FORM

12.13 DATUM FEATURES

Datum Features Versus Datum Feature Simulator

Datum Reference Frame

Datum Targets

- 12.14 POSITIONAL TOLERANCES
- 12.15 MAXIMUM MATERIAL CONDITION

Virtual Condition (VC)

12.16 TOLERANCES OF ANGLES



12.17 FORM TOLERANCES FOR SINGLE FEATURES

12.18 ORIENTATIONS FOR RELATED FEATURES

12.19 USING GEOMETRIC DIMENSIONING AND TOLERANCING

12.20 TOLERANCES AND DIGITAL PRODUCT DEFINITION

12.21 COMPUTER GRAPHICS

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

Design Project

Tolerancing Projects

CHAPTER THIRTEEN: THREADS, FASTENERS, AND SPRINGS

UNDERSTANDING THREADS AND FASTENERS

Screw Thread Terms

Screw Thread Forms

Thread Pitch

Thread Series

Right-Hand and Left-Hand Threads

Single and Multiple Threads

American National Thread Fits

Metric and Unified Thread Fits

Three Methods for Drawing Thread

13.1 THREAD NOTES

Acme Thread Notes

- 13.2 EXTERNAL THREAD SYMBOLS
- 13.3 INTERNAL THREAD SYMBOLS

13.4 DETAILED REPRESENTATION: METRIC, UNIFIED, AND AMERICAN NATIONAL THREADS

Detailed Internal Square Thread

Detailed External Square Thread

- 13.5 THREADS IN ASSEMBLY
- 13.6 MODELING THREAD
- 13.7 AMERICAN NATIONAL STANDARD PIPE THREADS
- 13.8 USE OF PHANTOM LINES
- 13.9 TAPPED HOLES



- 13.10 BOLTS, STUDS, AND SCREWS
- 13.11 STANDARD BOLTS AND NUTS
- 13.12 DRAWING STANDARD BOLTS
- 13.13 SPECIFICATIONS FOR BOLTS AND NUTS
- 13.14 LOCKNUTS AND LOCKING DEVICES
- 13.15 STANDARD CAP SCREWS
- 13.16 STANDARD MACHINE SCREWS
- 13.17 STANDARD SET SCREWS
- 13.18 AMERICAN NATIONAL STANDARD WOOD SCREWS
- 13.19 MISCELLANEOUS FASTENERS
- 13.20 KEYS
- 13.21 MACHINE PINS
- **13.22 RIVETS**

Riveted Joints

Rivet Symbols

Small Rivets

Blind Rivets

13.23 SPRINGS

Helical Springs

- 13.24 DRAWING HELICAL SPRINGS
- 13.25 MODELING SPRINGS

KEY WORDS

CHAPTER SUMMARY

REVIEW QUESTIONS

CHAPTER EXERCISES

Design Project

Thread and Fastener Projects

CHAPTER FOURTEEN WORKING DRAWINGS

WORKING DRAWINGS OR CONSTRUCTION DRAWINGS

Assembly Drawings

Detail Drawings or Piece Part Drawings

- 14.1 SUBASSEMBLIES
- 14.2 IDENTIFICATION

Multidetail Drawings



14.3 PARTS LISTS
14.4 ASSEMBLY SECTIONS
14.5 WORKING DRAWING ASSEMBLY
14.6 INSTALLATION ASSEMBLIES
14.7 CHECK ASSEMBLIES
14.8 WORKING DRAWING FORMATS
Number of Details per Sheet
Digital Drawing Transmittal
Title and Record Strips
14.9 DRAWING NUMBERS
14.10 ZONING
14.11 CHECKING DRAWINGS
14.12 DRAWING REVISIONS
14.13 SIMPLIFYING DRAWINGS
14.14 PATENT DRAWINGS
KEY WORDS
CHAPTER SUMMARY
REVIEW QUESTIONS
CHAPTER EXERCISES
Design Project
Working Drawing Exercises
GLOSSARY
Α
В
С
D
F
G
Н
I
J
K
L
M



Ν

Р

Q

R

S

Т

U

W

APPENDICES

INDEX

WORKSHEETS